

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Company David Shaver Manager	
OGM Pete Hess Environmental Scientist III	

Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Monday, December 07, 2009
Start Date/Time:	12/7/2009 8:35:00 AM
End Date/Time:	12/7/2009 9:10:00 AM
Last Inspection:	Tuesday, November 24, 2009

Inspector: Pete Hess, Environmental Scientist III

Weather: Winter storm warning in effect; cold; snowing.

InspectionID Report Number: 2213

Types of Operations

Accepted by: jhelfric

12/28/2009

Permitee: ANDALEX RESOURCES INC TOWER DIVISION
Operator: ANDALEX RESOURCES INC TOWER DIVISION

Site: WILDCAT LOADOUT

Address: 6750 AIRPORT RD, PO BOX 902 PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	100.00
Total Disturbed	
Phase I	
Phase II	
Phase III	

Mineral Ownership

✓ Federal
Underground

□ State
Surface

□ County
✓ Loadout

□ Fee
✓ Processing

□ Other
Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee is current relative to the required electronic quarterly submittals for surface water monitoring information. The Permittee continues to meet this special condition of the approved State permit.

The Wildcat site was covered with about 1/2 inch of fresh snow this AM.

Inspector's Signature:

Pete Hess, Environmental Scientist III

Date

Monday, December 07, 2009

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspector ID Number: 46

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, December 07, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	✓		V	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	V		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	V		V	
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		V		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓		V	
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing	✓		~	
16.1	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070033 Inspection Type: PARTIAL

Inspection Date: Monday, December 07, 2009

Page 3 of 3

4.a Hydrologic Balance: Diversions

The culvert inlets which were inspected appeared capable of functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

All ponds have snow covered bottoms. No melt water has accumulated.

4.d Hydrologic Balance: Water Monitoring

The Permittee's water monitoring contractor, Ms. Karla Knoop of JBR Environmental, notified the Division on December 8, 2009 that the third quarter 2009 water monitoring data for the Wildcat Loadout permit area was in the DOGM data base pipe line ready to be uploaded.

7. Coal Mine Waste, Refuse Piles, Impoundments

There was no activity occurring at the waste rock disposal site.

16.a Roads: Construction, Maintenance, Surfacing

Snow removal from the haul roads was occurring during today's inspection.